

Attorney Docket No. 1293.1338

ATTENTION

BRANCH

CERTIFICATE OF CORRECTION

ଏନ୍ୟାର୍ଥି United States Patent and Trademark Office

In re Patent Application of:

Young-hun MIN et al.

Application No.: 10/086,440

Confirmation No.: 4013

Filed: March 4, 2002

U.S. Patent No.: 6.765.711 B2

Issued: July 20, 2004

MICROMIRROR DRIVER AND METHOD OF CONTROLLING MICROMIRROR For:

DRIVER

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Certificate NOV 1 6 2004

Sir:

of Correction

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Michael D. Stein

Registration No. 37,240

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,765,711 DATED: July 20, 2004

INVENTOR(S): Young-hun MIN et al.

Column 14, line 19, "a" should be -- α --.

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700

Washington, DC 20005

PATENT NO. 6,765,711

No. of add'l copies @ 50¢ per page